
Contents

| | |
|--|------|
| Abstract | iii |
| Acknowledgments | v |
| Report Contributors | vii |
| Summary | ix |
| 1.0 Introduction | 1.1 |
| 1.1 Purpose and Scope | 1.1 |
| 1.2 Related Reports | 1.2 |
| 1.3 Groundwater/Vadose Zone Integration Project | 1.3 |
| 2.0 Groundwater | 2.1 |
| 2.1 Overview of Hanford Site Groundwater | 2.3 |
| 2.1.1 Groundwater Flow | 2.3 |
| 2.1.1.1 Current Water Table | 2.3 |
| 2.1.1.2 Water-Table Changes from June 1998 to March 1999 | 2.5 |
| 2.1.2 Groundwater Contaminants | 2.5 |
| 2.2 100 B/C Area | 2.15 |
| 2.2.1 Groundwater Flow | 2.15 |
| 2.2.2 Tritium | 2.15 |
| 2.2.3 Strontium-90 | 2.16 |
| 2.2.4 Chromium | 2.16 |
| 2.2.5 Nitrate | 2.16 |
| 2.2.6 Water Quality at Shoreline Monitoring Locations | 2.16 |
| 2.2.6.1 Aquifer Sampling Tube Results | 2.16 |
| 2.2.6.2 Riverbank Seepage Results | 2.16 |
| 2.3 100 K Area | 2.19 |
| 2.3.1 Groundwater Flow | 2.20 |
| 2.3.2 Chromium | 2.20 |
| 2.3.3 Strontium-90 | 2.21 |
| 2.3.4 Tritium | 2.22 |
| 2.3.5 Carbon-14 | 2.23 |

| | | |
|----------|---|------|
| 2.3.6 | Nitrate | 2.23 |
| 2.3.7 | Other Constituents of Interest | 2.23 |
| 2.3.7.1 | Plutonium | 2.23 |
| 2.3.7.2 | Trichloroethylene | 2.24 |
| 2.3.7.3 | Nickel | 2.24 |
| 2.3.8 | 100-K Fuel Storage Basins Monitoring | 2.24 |
| 2.3.8.1 | Groundwater Flow | 2.24 |
| 2.3.8.2 | Tritium | 2.25 |
| 2.3.9 | Groundwater Remediation | 2.26 |
| 2.3.9.1 | Interim Remedial Action Objectives | 2.26 |
| 2.3.9.2 | Remediation Progress During Fiscal Year 1999 | 2.26 |
| 2.3.9.3 | Influence on Aquifer Conditions | 2.27 |
| 2.3.10 | Water Quality at Shoreline Monitoring Locations | 2.27 |
| 2.3.10.1 | Aquifer Sampling Tubes | 2.27 |
| 2.3.10.2 | Riverbank Seepage | 2.28 |
| 2.3.10.3 | Special Shoreline Studies | 2.28 |
| 2.4 | 100 N Area | 2.43 |
| 2.4.1 | 1301-N and 1325-N Liquid Waste Disposal Facilities | 2.43 |
| 2.4.1.1 | Groundwater Flow | 2.43 |
| 2.4.1.2 | Tritium | 2.44 |
| 2.4.1.3 | Strontium-90 | 2.44 |
| 2.4.1.4 | Chromium | 2.45 |
| 2.4.1.5 | RCRA Parameters | 2.45 |
| 2.4.1.6 | Groundwater Remediation | 2.46 |
| 2.4.1.7 | Water Quality at Shoreline Monitoring Locations | 2.47 |
| 2.4.2 | 1324-N Surface Impoundment/1324-NA Percolation Pond | 2.48 |
| 2.4.2.1 | Groundwater Flow | 2.48 |
| 2.4.2.2 | RCRA Parameters | 2.48 |
| 2.4.2.3 | Sulfate and Specific Conductance | 2.48 |
| 2.4.3 | Other Groundwater Contamination | 2.49 |
| 2.4.3.1 | Petroleum Hydrocarbons | 2.49 |
| 2.4.3.2 | Nitrate | 2.49 |
| 2.4.3.3 | Manganese | 2.49 |
| 2.5 | 100 D Area | 2.63 |
| 2.5.1 | D and DR Reactors | 2.63 |
| 2.5.1.1 | Groundwater Flow | 2.63 |
| 2.5.1.2 | Chromium | 2.63 |
| 2.5.1.3 | Nitrate | 2.64 |
| 2.5.1.4 | Tritium | 2.64 |
| 2.5.1.5 | Strontium-90 | 2.64 |
| 2.5.1.6 | Groundwater Remediation | 2.65 |
| 2.5.2 | 120-D-1 Ponds | 2.66 |

| | | |
|---------|---|-------|
| 2.5.2.1 | Groundwater Flow | 2.67 |
| 2.5.2.2 | RCRA Parameters | 2.67 |
| 2.5.3 | Southwestern 100 D Area | 2.67 |
| 2.5.3.1 | Groundwater Flow | 2.67 |
| 2.5.3.2 | Chromium | 2.67 |
| 2.5.3.3 | Tritium | 2.69 |
| 2.5.4 | Waste Site Remediation | 2.69 |
| 2.5.5 | Water Quality at Shoreline Monitoring Locations | 2.70 |
| 2.5.5.1 | Aquifer Sampling Tube Results | 2.70 |
| 2.5.5.2 | Riverbank Seepage Results | 2.70 |
| 2.6 | 100 H Area | 2.83 |
| 2.6.1 | Groundwater Flow | 2.84 |
| 2.6.2 | Chromium | 2.84 |
| 2.6.3 | Strontium-90 | 2.85 |
| 2.6.4 | Tritium | 2.86 |
| 2.6.5 | Nitrate | 2.86 |
| 2.6.6 | 183-H Solar Evaporation Basins RCRA Monitoring | 2.86 |
| 2.6.6.1 | Groundwater Flow | 2.87 |
| 2.6.6.2 | Technetium-99 and Uranium | 2.87 |
| 2.6.6.3 | Nitrate | 2.87 |
| 2.6.6.4 | Chromium | 2.87 |
| 2.6.6.5 | Fluoride | 2.88 |
| 2.6.7 | Groundwater Remediation | 2.88 |
| 2.6.7.1 | Interim Remedial Action Objectives | 2.88 |
| 2.6.7.2 | Remediation Progress During Fiscal Year 1999 | 2.88 |
| 2.6.7.3 | Influence on Aquifer Conditions | 2.89 |
| 2.6.8 | Waste Site Remediation | 2.89 |
| 2.6.9 | Water Quality at Shoreline Monitoring Locations | 2.90 |
| 2.6.9.1 | Aquifer Sampling Tubes | 2.90 |
| 2.6.9.2 | Riverbank Seepage | 2.90 |
| 2.6.9.3 | Special Shoreline Studies | 2.90 |
| 2.7 | 100 F Area | 2.105 |
| 2.7.1 | Groundwater Flow | 2.105 |
| 2.7.2 | Tritium | 2.105 |
| 2.7.3 | Uranium | 2.106 |
| 2.7.4 | Strontium-90 | 2.106 |
| 2.7.5 | Nitrate | 2.106 |
| 2.7.6 | Chromium | 2.106 |
| 2.7.7 | Trichloroethylene | 2.106 |
| 2.7.8 | Water Quality at Shoreline Monitoring Locations | 2.106 |
| 2.7.8.1 | Aquifer Sampling Tube Results | 2.106 |
| 2.7.8.2 | Riverbank Seepage Results | 2.107 |

| | | |
|----------|---|-------|
| 2.8 | 200 West Area | 2.111 |
| 2.8.1 | Plutonium Finishing Plant | 2.111 |
| 2.8.1.1 | Groundwater Flow | 2.112 |
| 2.8.1.2 | Carbon Tetrachloride | 2.112 |
| 2.8.1.3 | Chloroform and Trichloroethylene | 2.114 |
| 2.8.1.4 | Plutonium and Americium | 2.114 |
| 2.8.1.5 | Nitrate | 2.114 |
| 2.8.1.6 | Low-Level Waste Management Area 4 RCRA Parameters | 2.114 |
| 2.8.1.7 | Groundwater Remediation at 200-ZP-1 Operable Unit | 2.115 |
| 2.8.2 | T Plant | 2.117 |
| 2.8.2.1 | Groundwater Flow | 2.118 |
| 2.8.2.2 | Tritium | 2.118 |
| 2.8.2.3 | Iodine-129 | 2.119 |
| 2.8.2.4 | Technetium-99 | 2.119 |
| 2.8.2.5 | Uranium and Gross Alpha | 2.119 |
| 2.8.2.6 | Nitrate | 2.119 |
| 2.8.2.7 | Chromium | 2.119 |
| 2.8.2.8 | Fluoride | 2.120 |
| 2.8.2.9 | Chlorinated Hydrocarbons | 2.120 |
| 2.8.2.10 | Iron, Manganese, and Nitrite | 2.120 |
| 2.8.2.11 | Waste Management Area T RCRA Assessment Summary | 2.120 |
| 2.8.2.12 | Waste Management Area TX-TY RCRA Assessment Summary | 2.122 |
| 2.8.2.13 | Low-Level Waste Management Area 3 RCRA Parameters | 2.124 |
| 2.8.3 | U Plant | 2.124 |
| 2.8.3.1 | Groundwater Flow | 2.125 |
| 2.8.3.2 | Uranium | 2.125 |
| 2.8.3.3 | Technetium-99 | 2.126 |
| 2.8.3.4 | Nitrate | 2.126 |
| 2.8.3.5 | Iodine-129 | 2.126 |
| 2.8.3.6 | 216-U-12 Crib RCRA Assessment Summary | 2.127 |
| 2.8.3.7 | Waste Management Area U RCRA Parameters | 2.128 |
| 2.8.3.8 | Groundwater Remediation at 200-UP-1 Operable Unit | 2.129 |
| 2.8.4 | REDOX Plant | 2.131 |
| 2.8.4.1 | Groundwater Flow | 2.131 |
| 2.8.4.2 | Tritium | 2.132 |
| 2.8.4.3 | Iodine-129 | 2.132 |
| 2.8.4.4 | Technetium-99 | 2.132 |
| 2.8.4.5 | Nitrate | 2.132 |
| 2.8.4.6 | Chromium | 2.133 |
| 2.8.4.7 | Trichloroethylene | 2.133 |
| 2.8.4.8 | Waste Management Area S-SX RCRA Assessment Summary | 2.133 |
| 2.8.4.9 | 216-S-10 Pond and Ditch RCRA Parameters | 2.137 |
| 2.8.5 | State-Approved Land Disposal System | 2.138 |
| 2.8.5.1 | Groundwater Flow | 2.138 |
| 2.8.5.2 | Extent of Contamination | 2.138 |

| | | |
|----------|---|-------|
| 2.9 | 200 East Area | 2.189 |
| 2.9.1 | B Plant | 2.189 |
| 2.9.1.1 | Groundwater Flow | 2.190 |
| 2.9.1.2 | Tritium | 2.190 |
| 2.9.1.3 | Iodine-129 | 2.190 |
| 2.9.1.4 | Technetium-99 | 2.191 |
| 2.9.1.5 | Uranium | 2.191 |
| 2.9.1.6 | Strontium-90 and Cesium-137 | 2.191 |
| 2.9.1.7 | Plutonium | 2.192 |
| 2.9.1.8 | Nitrate | 2.192 |
| 2.9.1.9 | Waste Management Area B-BX-BY Assessment Summary | 2.192 |
| 2.9.1.10 | 216-B-63 Trench RCRA Parameters | 2.196 |
| 2.9.1.11 | 200 East Low-Level Burial Grounds | 2.197 |
| 2.9.2 | PUREX Plant | 2.198 |
| 2.9.2.1 | Groundwater Flow | 2.198 |
| 2.9.2.2 | Tritium | 2.198 |
| 2.9.2.3 | Iodine-129 | 2.199 |
| 2.9.2.4 | Nitrate | 2.200 |
| 2.9.2.5 | Strontium-90 | 2.200 |
| 2.9.2.6 | Manganese | 2.200 |
| 2.9.2.7 | PUREX Cribs RCRA Parameters | 2.200 |
| 2.9.2.8 | Waste Management Area A-AX RCRA Parameters | 2.201 |
| 2.9.2.9 | Waste Management Area C RCRA Parameters | 2.203 |
| 2.9.2.10 | 216-A-29 Ditch RCRA Parameters | 2.204 |
| 2.9.2.11 | 216-B-3 Pond Parameters | 2.205 |
| 2.9.2.12 | Liquid Effluent Retention Facility | 2.207 |
| 2.9.2.13 | 200 Areas Treated Effluent Disposal Facility | 2.207 |
| 2.9.2.14 | Water Quality at Shoreline Monitoring Locations | 2.209 |
| 2.9.3 | Confined Aquifer in the Lower Ringold Formation | 2.209 |
| 2.9.3.1 | Groundwater Flow | 2.209 |
| 2.9.3.2 | Contaminant Distribution | 2.210 |
| 2.10 | 400 Area | 2.235 |
| 2.10.1 | Groundwater Flow | 2.235 |
| 2.10.2 | Nitrate and Nitrite | 2.235 |
| 2.10.3 | Tritium | 2.236 |
| 2.11 | 600 Area | 2.241 |
| 2.11.1 | Nonradioactive Dangerous Waste Landfill | 2.241 |
| 2.11.1.1 | Groundwater Flow | 2.241 |
| 2.11.1.2 | Resource Conservation and Recovery Act of 1976 Parameters | 2.242 |
| 2.11.2 | Solid Waste Landfill | 2.242 |
| 2.11.2.1 | WAC 173-304 Parameters | 2.243 |
| 2.11.2.2 | Site-Specific Parameters | 2.244 |

| | | |
|---------|---|-------|
| 2.11.3 | Gable Mountain Pond | 2.244 |
| 2.11.4 | 618-10 Burial Ground and 316-4 Crib | 2.245 |
| 2.11.5 | 618-11 Burial Ground | 2.246 |
| 2.11.6 | Central Plateau | 2.246 |
| 2.11.7 | Western 600 Area | 2.246 |
| 2.11.8 | 200-PO-1 Operable Unit | 2.247 |
| 2.12 | 300 Area | 2.255 |
| 2.12.1 | Groundwater Flow | 2.255 |
| 2.12.2 | Uranium | 2.256 |
| 2.12.3 | Strontium-90 | 2.257 |
| 2.12.4 | Chlorinated Hydrocarbons | 2.257 |
| 2.12.5 | Nitrate | 2.258 |
| 2.12.6 | 316-5 Process Trenches RCRA Parameters | 2.258 |
| 2.12.7 | 300-FF-1 and 300-FF-5 Operable Units | 2.258 |
| 2.12.8 | Water Quality at Shoreline Monitoring Locations | 2.259 |
| 2.13 | Richland North Area | 2.269 |
| 2.13.1 | Groundwater Flow | 2.269 |
| 2.13.2 | Tritium | 2.270 |
| 2.13.3 | Nitrate | 2.271 |
| 2.13.4 | Trichloroethylene | 2.271 |
| 2.13.5 | Gross Alpha and Uranium | 2.272 |
| 2.13.6 | Other Constituents | 2.272 |
| 2.14 | Upper-Basalt Confined Aquifer | 2.281 |
| 2.14.1 | Groundwater Flow | 2.281 |
| 2.14.2 | Groundwater Quality | 2.281 |
| 3.0 | Vadose Zone | 3.1 |
| 3.1 | 100 Areas | 3.3 |
| 3.1.1 | Soil Remediation at 116-C-1 Trench | 3.3 |
| 3.1.2 | Soil Sampling and Analysis at 1301-N and 1325-N Trenches | 3.4 |
| 3.1.3 | In Situ Gaseous Reduction Approach | 3.6 |
| 3.1.3.1 | Summary of Characterization Activities | 3.7 |
| 3.1.3.2 | Conclusions and Recommendations | 3.9 |
| 3.1.4 | Bench Scale Distribution Coefficient and Leach Studies on Hexavalent Chromium in Contaminated Vadose Zone Sediment from 100 D Area | 3.10 |
| 3.1.4.1 | Samples and Methods | 3.10 |
| 3.1.4.2 | Results | 3.11 |
| 3.1.4.3 | Conclusion | 3.11 |
| 3.2 | 200 Areas | 3.27 |
| 3.2.1 | 200 Areas Characterization Activities | 3.27 |

| | | |
|---------|--|------|
| 3.2.1.1 | Decommissioning of Borehole 41-09-39 at the SX Tank Farm | 3.27 |
| 3.2.1.2 | New Vadose Zone Borehole at Single-Shell Tank SX-115 | 3.29 |
| 3.2.1.3 | Temperature and Other Geophysical Logging at Single-Shell Tank Farms | 3.30 |
| 3.2.1.4 | Baseline Spectral Gamma-Ray Logging at B and T Tank Farms | 3.30 |
| 3.2.2 | 200 Areas Monitoring Activities | 3.34 |
| 3.2.2.1 | Carbon Tetrachloride Monitoring and Remediation | 3.34 |
| 3.2.2.2 | Rapid Scan Gross Gamma-Ray Logging at Single-Shell Tank C-106 | 3.38 |
| 3.2.2.3 | Spectral Gamma-Ray and Neutron Moisture Monitoring of 200 East Area Specific Retention Facilities | 3.39 |
| 3.3 | Additional Vadose Zone Related Investigations | 3.69 |
| 3.3.1 | Hanford Site Lysimeters | 3.69 |
| 3.3.2 | Hanford Site Surface Barrier Technology | 3.69 |
| 3.3.2.1 | Results of Field Tests | 3.70 |
| 3.3.2.2 | Conclusions | 3.72 |
| 3.3.3 | Measurement of Tritium in Soil Moisture and Helium-3 in Soil Gas at the Old Hanford Townsite and KE Reactor | 3.72 |
| 3.3.3.1 | Experimental Methods | 3.73 |
| 3.3.3.2 | Results and Discussion | 3.74 |
| 3.3.3.3 | Conclusions | 3.75 |
| 4.0 | Groundwater Modeling | 4.1 |
| 4.1 | Site-Wide Groundwater Model Consolidation Process | 4.1 |
| 4.1.1 | Recommendations for a Site-Wide Groundwater Flow and Transport Model | 4.2 |
| 4.1.2 | External Peer Review of the Recommended Site-Wide Groundwater Model | 4.3 |
| 4.1.3 | Response to Peer Review | 4.5 |
| 4.1.4 | Model Applications | 4.6 |
| 4.2 | Modeling to Support Pump-and-Treat Operations | 4.6 |
| 4.2.1 | Model Results for 100-KR-4, 100-NR-2, and 100-HR-3 Operable Units | 4.7 |
| 4.2.2 | Model Results for 200-UP-1 Operable Unit | 4.7 |
| 4.2.3 | Model Results for 200-ZP-1 Operable Unit | 4.8 |
| 5.0 | Well Installation, Maintenance, and Decommissioning | 5.1 |
| 5.1 | Well Installation | 5.1 |
| 5.2 | Well Maintenance | 5.1 |
| 5.3 | Well Decommissioning | 5.2 |
| 6.0 | References | 6.1 |
| | Appendix A - Support Information | A.1 |
| | Appendix B - Quality Assurance and Quality Control | B.1 |

Tables

| | | |
|--------|---|-------|
| 2.1-1 | Maximum Concentrations of Groundwater Contaminants in Fiscal Year 1999 | 2.7 |
| 2.3-1 | Summary of 100 K Area Pump-and-Treat Performance for Fiscal Year 1999..... | 2.29 |
| 2.4-1 | Summary of 100 N Area Pump-and-Treat Performance for Fiscal Year 1999 | 2.50 |
| 2.5-1 | Summary of 100 D Area Pump-and-Treat Performance for Fiscal Year 1999 | 2.71 |
| 2.6-1 | Performance Statistics for the 100 H Pump-and-Treat System for Chromium, Fiscal Year 1999 | 2.92 |
| 2.6-2 | Chromium and Strontium-90 Results for River Substrate Pore Water Samples | 2.92 |
| 2.8-1 | Volume of Groundwater Treated and Mass of Carbon Tetrachloride Removed Since Startup of Operations at 200-ZP-1 | 2.140 |
| 2.8-2 | Average Carbon Tetrachloride Concentrations for Each of the Extraction Wells and the Influent Tank at 200-ZP-1 During Fiscal Year 1999 | 2.140 |
| 2.8-3 | Results from Discrete Level Groundwater Sampling During Drilling of Well 299-W10-24 | 2.141 |
| 2.8-4 | Results of Discrete Level Sampling During Drilling of Well 299-W14-14 | 2.141 |
| 2.8-5 | Quantity of Treated Groundwater and Contaminant Mass Removed Since Initiation of 200-UP-1 Pump-and-Treat Operations | 2.142 |
| 2.8-6 | Summary of Contaminant Trends in the Extraction Well at 200-UP-1 | 2.142 |
| 2.8-7 | Comparison of Filtered and Unfiltered Metal Results on August 9, 1999 for Well 299-W23-15 | 2.143 |
| 2.11-1 | Ranges of Chlorinated Hydrocarbon Concentrations in Groundwater at the Solid Waste Landfill, December 1998 to August 1999 | 2.248 |
| 2.11-2 | Uranium Isotopic Composition in Well 699-S6-E4A..... | 2.249 |
| 3.1-1 | Average 4-Day Contact Time K_d and Standard Deviation for Hexavalent Chromium and Total Chromium Adsorption..... | 3.12 |
| 3.1-2 | Average 14-Day Contact Time K_d and Standard Deviation for Hexavalent Chromium and Total Chromium Adsorption..... | 3.12 |
| 3.2-1 | Composition of Sediment from Borehole 41-09-39 in SX Tank Farm | 3.44 |

| | | |
|-------|--|------|
| 3.2-2 | Water Leachable Chemicals in Sediment from Borehole 41-09-39 in SX Tank Farm | 3.44 |
| 3.2-3 | Acid Extractable Chemicals from Sediment from Borehole 41-09-39 in SX Tank Farm | 3.45 |
| 3.2-4 | Estimates of Mobility of Cesium, Technetium, and Chromium in Samples from Borehole 41-09-39, Based on the Percent of the Constituent Leached by Water | 3.45 |
| 3.2-5 | Calculated In Situ Distribution Coefficients for Samples from Borehole 41-09-39 in SX Tank Farm | 3.46 |
| 3.2-6 | Carbon Tetrachloride Inventory in Primary Disposal Sites | 3.46 |
| 3.2-7 | Liquid Disposal Facilities and Associated Boreholes and Wells Monitored with Spectral Gamma-Ray and Neutron Moisture Tools, Fiscal Year 1999 | 3.47 |
| 3.3-1 | Lysimeters at the Hanford Site | 3.76 |
| 5.1-1 | Well Installations for Fiscal Year 1999 | 5.3 |
| 5.2-1 | Well Maintenance Summary | 5.3 |
| 5.3-1 | Wells Decommissioned in Fiscal Year 1999 | 5.4 |

Figures

| | | |
|-------|--|-------|
| S.1 | Distribution of Major Radionuclides in Groundwater at Concentrations Above Maximum Contaminant Levels or Interim Drinking Water Standards, Fiscal Year 1999 | xxii |
| S.2 | Distribution of Major Hazardous Chemicals in Groundwater at Concentrations Above Maximum Contaminant Levels, Fiscal Year 1999 | xxiii |
| S.3 | Potential Dose Estimates from Ingestion of Groundwater, Fiscal Year 1999 | xxiv |
| S.4 | Cancer-Risk Estimates from Ingestion of Groundwater, Fiscal Year 1999 | xxv |
| S.5 | Hazard Quotient Estimates from Ingestion of Groundwater, Fiscal Year 1999 | xxvi |
| 2.1-1 | Hanford Site and Outlying Areas Water-Table Map, March 1999 | 2.9 |
| 2.1-2 | Changes in Water-Table Elevations Between June 1998 and March 1999 | 2.10 |

| | | |
|--------|--|------|
| 2.1-3 | Average Tritium Concentrations on the Hanford Site, Top of Unconfined Aquifer | 2.11 |
| 2.1-4 | Average Nitrate Concentrations on the Hanford Site, Top of Unconfined Aquifer | 2.12 |
| 2.1-5 | Average Iodine-129 Concentrations on the Hanford Site, Top of Unconfined Aquifer | 2.13 |
| 2.1-6 | Groundwater Operable Units on the Hanford Site | 2.14 |
| 2.2-1 | Tritium in Wells at 100 B/C Area | 2.17 |
| 2.2-2 | Nitrate in Well 199-B3-47 Near 116-B-11 Retention Basin | 2.18 |
| 2.2-3 | Nitrate in Wells 199-B2-13 and 699-72-92, West of 100 B/C Area | 2.18 |
| 2.3-1 | Influence of Groundwater Mound During the 100 K Operating Years, 1955 to 1971 | 2.29 |
| 2.3-2 | Average Chromium Concentrations in 100 K Areas, Top of Unconfined Aquifer | 2.30 |
| 2.3-3 | Chromium in Wells Near KW Reactor | 2.31 |
| 2.3-4 | Strontium-90 in Wells Near 116-K-2 Liquid Waste Disposal Trench | 2.31 |
| 2.3-5 | Strontium-90 and Tritium in Wells Near KE Reactor | 2.32 |
| 2.3-6 | Strontium-90 in Wells Near KW Reactor | 2.32 |
| 2.3-7 | Tritium in Wells Downgradient of KE Fuel Storage Basin | 2.33 |
| 2.3-8 | Tritium in Wells Northeast of KE Reactor | 2.34 |
| 2.3-9 | Carbon-14 in Wells Near KE Gas Condensate Crib | 2.34 |
| 2.3-10 | Carbon-14 in Wells Near KW Gas Condensate Crib | 2.35 |
| 2.3-11 | Example of Increasing Nitrate in Wells at 100 K Area | 2.35 |
| 2.3-12 | Trichloroethylene in Wells Near KW Reactor | 2.36 |
| 2.3-13 | Nickel in Well 199-K-36 | 2.36 |
| 2.3-14 | Tritium in Wells Adjacent to KE Fuel Storage Basin | 2.37 |
| 2.3-15 | Tritium in Wells Adjacent to KW Fuel Storage Basin | 2.38 |
| 2.3-16 | Tritium and Specific Conductance in Wells Near KE Gas Condensate Crib | 2.39 |

| | | |
|--------|---|------|
| 2.3-17 | Tritium and Specific Conductance in Wells Near KW Gas Condensate Crib | 2.39 |
| 2.3-18 | Capture Zone from 100-KR-4 Pump-and-Treat System | 2.40 |
| 2.3-19 | Chromium in Upstream Near-River Extraction Wells | 2.41 |
| 2.3-20 | Chromium in Downstream Near-River Extraction Wells..... | 2.41 |
| 2.3-21 | Chromium in Compliance Wells..... | 2.42 |
| 2.4-1 | Water Levels in Wells Monitoring 100 N Area | 2.50 |
| 2.4-2 | Tritium in Wells Monitoring 100 N Area | 2.51 |
| 2.4-3 | Average Strontium-90 Concentrations in 100 N Area, Top of Unconfined Aquifer | 2.52 |
| 2.4-4 | Strontium-90 and Water Levels in Well 199-N-67 Near 1301-N Facility | 2.53 |
| 2.4-5 | Strontium-90 in Wells Near 1325-N Facility | 2.53 |
| 2.4-6 | Groundwater Capture Zone from 100 N Area Pump-and-Treat System | 2.54 |
| 2.4-7 | Total Organic Carbon in Well 199-N-59 Monitoring 1324-N/NA Site..... | 2.55 |
| 2.4-8 | Specific Conductance in 100 N Area, Top of Unconfined Aquifer | 2.56 |
| 2.4-9 | Specific Conductance and Sulfate in Wells Monitoring 1324-N/NA Facilities | 2.57 |
| 2.4-10 | Nitrate Concentrations in 100 N Area, Top of Unconfined Aquifer | 2.58 |
| 2.4-11 | Nitrate in Wells Monitoring 100 N Area..... | 2.59 |
| 2.4-12 | Nitrate in Wells 199-N-16 and 199-N-18 | 2.60 |
| 2.4-13 | Manganese in Wells 199-N-16 and 199-N-18 | 2.61 |
| 2.5-1 | Average Chromium Concentrations in 100 D and 100 H Areas, Top of Unconfined Aquifer | 2.73 |
| 2.5-2 | Chromium and Specific Conductance in Well 199-D5-15, North of D Reactor | 2.75 |
| 2.5-3 | Strontium-90 and Water Levels in Well 199-D8-68, Northern 100 D Area | 2.75 |
| 2.5-4 | Capture Zone from 100-HR-3 Pump-and-Treat System | 2.76 |

| | | |
|--------|---|-------|
| 2.5-5 | Chromium in Compliance Wells for 100-HR-3 Pump-and-Treat System | 2.77 |
| 2.5-6 | Chromium in Extraction Wells for 100-HR-3 Pump-and-Treat System | 2.77 |
| 2.5-7 | Specific Conductance in Wells Monitoring D Ponds | 2.78 |
| 2.5-8 | pH in Wells Monitoring D Ponds | 2.78 |
| 2.5-9 | Chromium in Wells Monitoring Redox Demonstration | 2.79 |
| 2.5-10 | Sulfate in Wells 199-D4-13, 199-D4-14, and 199-D4-15, Near Redox Demonstration | 2.80 |
| 2.5-11 | Tritium in Wells 199-D2-6 and 699-87-55 at 100 D Area, South of 100 D Area | 2.81 |
| 2.6-1 | Chromium in Wells 699-96-43 and 699-97-43 Between 100 H and 100 D Areas | 2.93 |
| 2.6-2 | Chromium in Wells 199-H3-1, 199-H4-47, and 199-H4-48 Near H Reactor | 2.93 |
| 2.6-3 | Chromium in Wells 199-H4-14, 199-H4-16, and 199-H4-18 at 100 H Area | 2.94 |
| 2.6-4 | Chromium in Wells 199-H3-2A, 199-H3-2B, and 199-H3-2C at 100 H Area | 2.94 |
| 2.6-5 | Chromium in Wells 199-H4-12A, 199-H4-12B, and 199-H4-12C at 100 H Area | 2.95 |
| 2.6-6 | Strontium-90 and Gross Beta in Well 199-H4-11 | 2.95 |
| 2.6-7 | Tritium in Wells 199-H3-1, 199-H4-47, and 199-H4-48 Northeast of H Reactor | 2.96 |
| 2.6-8 | Tritium in Wells 699-96-43 and 699-97-43 Between 100 D and 100 H Areas | 2.96 |
| 2.6-9 | Tritium in Wells 199-H3-2A, 199-H3-2B, and 199-H3-2C, Western 100 H Area | 2.97 |
| 2.6-10 | Example of Increasing Nitrate in Wells at 100 H Area | 2.97 |
| 2.6-11 | Water Levels in Well 199-H4-3 Monitoring 183-H Solar Evaporation Basins | 2.98 |
| 2.6-12 | Technetium-99 and Uranium in Wells 199-H4-3 and 199-H4-4 Monitoring 183-H Solar Evaporation Basins | 2.99 |
| 2.6-13 | Contaminants in Well 199-H4-5 Near the 183-H Solar Evaporation Basins | 2.100 |
| 2.6-14 | Technetium-99 and Nitrate in Well 199-H4-18 | 2.101 |
| 2.6-15 | Chromium in Wells 199-H4-3 and 199-H4-4 Monitoring 183-H Solar Evaporation Basins | 2.102 |

| | | |
|--------|---|-------|
| 2.6-16 | Capture Zone from 100-HR-3 Pump-and-Treat System | 2.103 |
| 2.6-17 | Chromium in Pump-and-Treat Compliance Wells | 2.104 |
| 2.6-18 | Chromium in Pump-and-Treat Extraction Wells | 2.104 |
| 2.7-1 | Strontium-90 in Wells 199-F5-1 and 199-F5-3 Near 116-F-2 Trench | 2.108 |
| 2.7-2 | Nitrate in Well 199-F7-1, Southwestern 100 F Area, and Well 199-F5-45, Northeast of F Reactor | 2.109 |
| 2.8-1 | Average Carbon Tetrachloride Concentrations in 200 West Area, Top of Unconfined Aquifer | 2.145 |
| 2.8-2 | Carbon Tetrachloride in Well 299-W15-1 Near Northern Extraction Wells | 2.147 |
| 2.8-3 | Carbon Tetrachloride in Wells 299-W10-19 and 299-W10-20, Northwestern 200 West Area | 2.147 |
| 2.8-4 | Carbon Tetrachloride in Wells 299-W11-14 and 299-W11-7, Northwestern 200 West Area | 2.148 |
| 2.8-5 | Carbon Tetrachloride Concentrations in Wells Monitoring 200 West Area, Top of Unconfined Aquifer | 2.149 |
| 2.8-6 | Carbon Tetrachloride Concentrations in the Middle Unconfined Aquifer, 200 West Area, Compared to Concentration Contours at the Top of the Unconfined Aquifer | 2.150 |
| 2.8-7 | Carbon Tetrachloride Concentrations in the Lower Unconfined Aquifer, 200 West Area, Compared to Concentration Contours at the Top of the Unconfined Aquifer | 2.151 |
| 2.8-8 | Average Chloroform Concentrations in 200 West Area, Top of Unconfined Aquifer | 2.153 |
| 2.8-9 | Average Trichloroethylene Concentrations in 200 West Area, Top of Unconfined Aquifer | 2.155 |
| 2.8-10 | Average Nitrate Concentrations in the Western and Northern 200 West Area, Top of Unconfined Aquifer | 2.156 |
| 2.8-11 | Nitrate in Wells 299-W18-23 and 299-W18-26, Western 200 West Area | 2.157 |
| 2.8-12 | Carbon Tetrachloride in Northern Extraction Wells for 200-ZP-1 Pump-and-Treat System | 2.157 |
| 2.8-13 | Carbon Tetrachloride in Southern Extraction Wells for 200-ZP-1 Pump-and-Treat System | 2.158 |
| 2.8-14 | 200-ZP-1 Carbon Tetrachloride Remediation Area Plume, July 1999 | 2.159 |
| 2.8-15 | 200-ZP-1 Carbon Tetrachloride Baseline Plume for the Remediation Area, June 1996 | 2.160 |

| | | |
|--------|--|-------|
| 2.8-16 | Water Table for September 1999, Vicinity of the 200-ZP-1 Remediation | 2.161 |
| 2.8-17 | Pump-and-Treat System Estimated Area of Hydraulic Capture as of September 1999 | 2.162 |
| 2.8-18 | Tritium in Wells 299-W14-2, 299-W14-12, and 299-W14-13, East of TY Tank Farm | 2.163 |
| 2.8-19 | Average Iodine-129 Concentrations in Northern 200 West Area, Top of Unconfined Aquifer | 2.164 |
| 2.8-20 | Average Technetium-99 Concentrations in Northern 200 West Area, Top of Unconfined Aquifer | 2.165 |
| 2.8-21 | Average Filtered Chromium Concentrations Near Waste Management Areas T and TX-TY, Top of Unconfined Aquifer | 2.166 |
| 2.8-22 | Technetium-99 in Wells 299-W11-27, 299-W11-23, and 299-W10-24, North of T Tank Farm | 2.167 |
| 2.8-23 | Nitrate in Wells 299-W11-27 and 299-W10-24, North of T Tank Farm | 2.167 |
| 2.8-24 | Technetium-99 in Wells 299-W14-12 and 299-W14-13, East of TX-TY Tank Farms | 2.168 |
| 2.8-25 | Chromium in Wells 299-W14-12 and 299-W14-13, East of TX-TY Tank Farms | 2.168 |
| 2.8-26 | Technetium-99 in Well 299-W15-4, South of TX-TY Tank Farms | 2.169 |
| 2.8-27 | Average Uranium Concentrations in Eastern 200 West Area, Top of Unconfined Aquifer | 2.170 |
| 2.8-28 | Uranium in Well 299-W19-3 Near the 216-U-1 and 216-U-2 Cribs | 2.171 |
| 2.8-29 | Technetium-99 in Well 299-W19-29 Near U Plant | 2.171 |
| 2.8-30 | Technetium-99 in Well 699-38-70, East of U Plant | 2.172 |
| 2.8-31 | Average Nitrate Concentrations in Southern and Eastern 200 West Area, Top of Unconfined Aquifer | 2.173 |
| 2.8-32 | Average Iodine-129 Concentrations in Southern and Eastern 200 West Area, Top of Unconfined Aquifer | 2.174 |
| 2.8-33 | Nitrate in Wells Near the 216-U-12 Crib | 2.175 |
| 2.8-34 | Technetium-99 in Wells Near the 216-U-12 Crib | 2.176 |
| 2.8-35 | 200-UP-1 Technetium-99 Plume, July 1999 | 2.177 |
| 2.8-36 | 200-UP-1 Technetium-99 Baseline Plume, June 1995 | 2.178 |

| | | |
|--------|--|-------|
| 2.8-37 | 200-UP-1 Uranium Plume, July 1999 | 2.179 |
| 2.8-38 | 200-UP-1 Uranium Baseline Plume, June 1995 | 2.180 |
| 2.8-39 | 200-UP-1 Pump-and-Treat System Estimated Area of Hydraulic Capture as of September 1999 | 2.181 |
| 2.8-40 | 200-UP-1 Pump-and-Treat System Steady State Hydraulic Capture Zone Beginning March 1997 ... | 2.182 |
| 2.8-41 | Tritium in Well 699-38-65, East of 200 West Area REDOX Plant | 2.183 |
| 2.8-42 | Tritium in Wells 299-W23-9 and 299-W22-46 Near the 216-S-25 Crib and S-SX Tank Farms | 2.183 |
| 2.8-43 | Average Technetium-99 Concentrations Near S-SX Tank Farms, Top of Unconfined Aquifer | 2.184 |
| 2.8-44 | Chromium in Well 299-W26-7, Monitoring 216-S-10 Pond and Ditch | 2.185 |
| 2.8-45 | Technetium-99, Chromium, and Nitrate in Wells at Waste Management Area S-SX | 2.186 |
| 2.8-46 | Technetium-99 in Well 299-W22-46, Southeast of Waste Management Area SX | 2.187 |
| 2.8-47 | Water Levels for Well 699-48-77A | 2.187 |
| 2.8-48 | Tritium in Wells Monitoring the State-Approved Land Disposal Site | 2.188 |
| 2.8-49 | Sulfate in Wells Monitoring State-Approved Land Disposal Site | 2.188 |
| 2.9-1 | Tritium in B Plant Area | 2.211 |
| 2.9-2 | Average Iodine-129 Concentrations in 200 East Area, Extending Northwest Toward Gable Gap, Top of Unconfined Aquifer | 2.212 |
| 2.9-3 | Iodine-129 in the Gable Gap and Old Hanford Townsite Areas | 2.213 |
| 2.9-4 | Average Technetium-99 Concentrations, Northern 200 East Area, Top of Unconfined Aquifer | 2.214 |
| 2.9-5 | Average Nitrate Concentrations in 200 East Area, Top of Unconfined Aquifer | 2.215 |
| 2.9-6 | Hydrographs of Wells Located North, East, West, and Southwest of Waste Management Area B-BX-BY | 2.216 |
| 2.9-7 | Technetium-99 in Wells at Waste Management Area B-BX-BY | 2.216 |
| 2.9-8 | Nitrate in Wells at Waste Management Area B-BX-BY | 2.217 |
| 2.9-9 | Technetium-99 in at Waste Management Area B-BX-BY | 2.217 |

| | | |
|--------|---|-------|
| 2.9-10 | Nitrate and Technetium-99 in Well 299-E33-16 at Waste Management Area B-BX-BY | 2.218 |
| 2.9-11 | Technetium-99 and Uranium at Well 299-E33-41 at Waste Management Area B-BX-BY | 2.218 |
| 2.9-12 | Ratio of Nitrate to Technetium-99, April through June 1999 | 2.219 |
| 2.9-13 | Tritium in Well 299-E17-9 at 216-A-36B Crib | 2.220 |
| 2.9-14 | Tritium in Well 699-40-1 at the 600 Area Near the Old Hanford Townsite | 2.220 |
| 2.9-15 | Tritium in Well 699-24-33 Near the Central Landfill | 2.221 |
| 2.9-16 | Iodine-129 in Well 299-E17-9 at the 216-A-36B Crib | 2.221 |
| 2.9-17 | Manganese at 216-A-37-1 Crib | 2.222 |
| 2.9-18 | Hydrographs of Wells at Waste Management Area A-AX Using NAVD88 | 2.222 |
| 2.9-19 | Nitrate, Sulfate, and Technetium-99 in Wells at Waste Management Area A-AX | 2.223 |
| 2.9-20 | Tritium and Nitrate in Well 299-E24-20 at Waste Management Area A-AX | 2.224 |
| 2.9-21 | Chromium, Iron, Manganese, and Nickel in Well 299-E24-19 at Waste Management Area A-AX | 2.224 |
| 2.9-22 | Technetium-99 and Nitrate in Well 299-E25-46 at Waste Management Area A-AX | 2.225 |
| 2.9-23 | Hydrographs of Wells at Waste Management Area C | 2.225 |
| 2.9-24 | Nitrate at Waste Management Area C | 2.226 |
| 2.9-25 | Nitrate, Chloride, and Sodium in Well 299-E27-14 at Waste Management Area C | 2.226 |
| 2.9-26 | Technetium-99 at Waste Management Area C | 2.227 |
| 2.9-27 | Nitrate and Technetium-99 in Well 299-E27-14 at Waste Management Area C | 2.227 |
| 2.9-28 | Hydrographs of Wells at the 216-A-29 Ditch | 2.228 |
| 2.9-29 | Sulfate in Wells Monitoring 216-A-29 Ditch | 2.228 |
| 2.9-30 | Hydrographs of Wells at the 216-B-3 Pond | 2.229 |
| 2.9-31 | Potentiometric Surface Map of Unit 7 for the Vicinity of the Treated Effluent Disposal Facility | 2.230 |

| | | |
|--------|--|-------|
| 2.9-32 | Hydrographs of Wells at the Treated Effluent Disposal Facility | 2.231 |
| 2.9-33 | Potentiometric Surface Map of Ringold Formation Confined Aquifer, Central Hanford Site, March 1999 | 2.232 |
| 2.9-34 | Water Levels in Wells 299-E25-28 and 299-E25-34 | 2.233 |
| 2.9-35 | Major Ion Chemistry and Tritium Concentrations for Confined and Unconfined Groundwater Near 216-B-3 Pond and the Treated Effluent Disposal Facility | 2.234 |
| 2.10-1 | Average Nitrate in Wells at 400 Area | 2.237 |
| 2.10-2 | Nitrate in 600 Area Wells Near 400 Area | 2.238 |
| 2.10-3 | Nitrite in 600 Area Wells Near 400 Area | 2.238 |
| 2.10-4 | Average Tritium in Wells at 400 Area | 2.239 |
| 2.10-5 | Comparison of Tritium Concentrations in 400 Area Drinking Water System | 2.240 |
| 2.11-1 | Average Strontium-90 Concentrations at Gable Mountain Pond, Top of Unconfined Aquifer | 2.250 |
| 2.11-2 | Strontium-90 in Wells 699-53-47B and 699-53-48A Near Gable Mountain Pond | 2.251 |
| 2.11-3 | Uranium in Well 699-S6-E4A Near 618-10 Burial Ground | 2.251 |
| 2.11-4 | Tributyl Phosphate in Well 699-S6-E4A Near 618-10 Burial Ground | 2.252 |
| 2.11-5 | Gross Beta Concentrations in Well 699-13-3A Near 618-11 Burial Ground | 2.252 |
| 2.11-6 | Average Nitrate Concentrations in Western 600 Area, Top of Unconfined Aquifer | 2.253 |
| 2.12-1 | Average Uranium Concentrations at 300 Area, Top of Unconfined Aquifer | 2.260 |
| 2.12-2 | Uranium in Well 399-1-17A Near 316-5 Process Trenches | 2.261 |
| 2.12-3 | Uranium in Wells 399-3-11 and 399-4-9 Near 324 Building | 2.261 |
| 2.12-4 | Trichloroethylene in Well 399-1-16B Near 316-5 Process Trenches | 2.262 |
| 2.12-5 | Average Trichloroethylene Concentrations in the 300 Area and Richland North Area, Top of Unconfined Aquifer | 2.263 |
| 2.12-6 | Trichloroethylene in Well 399-4-1, Southern 300 Area | 2.264 |

| | | |
|---------|---|-------|
| 2.12-7 | cis-1,2-Dichloroethylene in Well 399-1-16B Near 316-5 Process Trenches | 2.264 |
| 2.12-8 | Average Tetrachloroethylene Concentrations in the 300 Area, Top of Unconfined Aquifer | 2.265 |
| 2.12-9 | Tetrachloroethylene in Well 399-1-17A Near 316-5 Process Trenches | 2.266 |
| 2.12-10 | Nitrate in Wells at the 300 Area and Richland North Area | 2.267 |
| 2.13-1 | Water Levels in Wells Monitoring the Richland North Area, March 1999 | 2.273 |
| 2.13-2 | Water Levels in Well SPC-GM-2 at Siemens Power Corporation | 2.275 |
| 2.13-3 | Water Levels in Well 699-S31-1 | 2.275 |
| 2.13-4 | Tritium Concentrations in Wells at 300 and Richland North Areas, Top of Unconfined Aquifer | 2.277 |
| 2.13-5 | Nitrate in Wells 699-S38-E11, 699-S36-13A, and 699-S38-E12A | 2.279 |
| 2.13-6 | Trichloroethylene in Well 699-S31-E10A | 2.279 |
| 2.14-1 | Potentiometric Map of Upper Basalt-Confined Aquifer System, March 1999 | 2.285 |
| 2.14-2 | Upper Basalt-Confined Aquifer System Hydraulic Head in Wells Near B Pond | 2.286 |
| 2.14-3 | Hanford Site Map Showing Upper Basalt-Confined Aquifer Wells | 2.287 |
| 3.1-1 | Cross Section of the 116-C-1 Trench Showing Location of the Test Pit and Distribution of Samples | 3.13 |
| 3.1-2 | Analytical Results versus Depth for Selected Constituents in the 116-C-1 Trench Test Pit | 3.14 |
| 3.1-3 | Map of the 1301-N Crib and Trench Showing the Locations of Samples Collected | 3.15 |
| 3.1-4 | Map of the 1325-N Crib and Trench Showing the Locations of Samples Collected | 3.16 |
| 3.1-5 | Concentration versus Distance from the 1301-N Crib for Selected Analytes in Samples from the 1301-N Trench | 3.17 |
| 3.1-6 | Concentration of Selected Analytes in Surface Samples from the 1325-N Crib | 3.18 |
| 3.1-7 | Activity versus Depth for Selected Analytes in Test Pit Samples from the 1301-N and 1325-N Trenches | 3.19 |
| 3.1-8 | In Situ Gaseous Reduction System and Well Field Network | 3.20 |

| | | |
|--------|--|------|
| 3.1-9 | Facilities, Wells, and Hexavalent Chromium Groundwater Plumes in 100 D Area | 3.21 |
| 3.1-10 | Map of Sample Locations at the 183-DR Head House and Filter Plant Site | 3.22 |
| 3.1-11 | Map of Sample Locations at the 190-D Complex | 3.23 |
| 3.1-12 | Map of Sample Locations at the 183-H Solar Evaporation Basins | 3.24 |
| 3.1-13 | Map of Sample Locations at the 183-KW Chromate Transfer Station | 3.25 |
| 3.1-14 | Effluent Hexavalent Chromium Concentrations versus Pore Volumes for Leach Test Samples | 3.26 |
| 3.2-1 | Temperature Distribution in Borehole 41-09-39 | 3.48 |
| 3.2-2 | Neutron-Gamma Capture Spectroscopy Log from the New Borehole at Single-Shell Tank SX-115 | 3.49 |
| 3.2-3 | Map of B Tank Farm with Layout of Tanks and Locations of Monitoring Boreholes | 3.50 |
| 3.2-4 | Map of T Tank Farm with Layout of Tanks and Locations of Monitoring Boreholes | 3.51 |
| 3.2-5 | Selected Spectral Gamma-Ray Logs of Radionuclides Around Boreholes in T Tank Farm Showing Concentrations of Contaminants versus Depth | 3.52 |
| 3.2-6 | Selected Spectral Gamma-Ray Logs of Radionuclides Around Boreholes Near Tank T-106 in T Tank Farm Showing Concentrations of Contaminants versus Depth | 3.54 |
| 3.2-7 | Time Series Concentrations of Carbon Tetrachloride in Soil Vapor Extracted from the 216-Z-9 Well Field and the 216-Z-1A/-12/-18 Well Fields | 3.56 |
| 3.2-8 | Conceptual Model of Carbon Tetrachloride and Wastewater Migration Beneath 216-Z-9 Trench | 3.57 |
| 3.2-9 | Location Map for Boreholes Logged at Single-Shell Tank C-106 | 3.58 |
| 3.2-10 | Time Series Gross Gamma-Ray Logs from Borehole 30-06-02 | 3.59 |
| 3.2-11 | Time Series Gross Gamma-Ray Logs from Borehole 30-06-03 | 3.60 |
| 3.2-12 | Map of the 200 East Area Showing Locations of Facilities Monitored, Fiscal Year 1999 | 3.61 |
| 3.2-13 | Comparison of 1999 and 1976 Gross Gamma-Ray Logs from Borehole 299-E24-53 at the 216-A-2 Crib | 3.62 |

| | | |
|---------|---|------|
| 3.2-14 | Comparison of 1999 and 1992 Spectral Gamma-Ray Logs for Cesium-137 from Well 299-E13-1 at the 216-B-14 Crib and Well 299-E13-5 at the 216-B-18 Crib | 3.63 |
| 3.2-15 | Comparison of 1999 and 1976 Gross Gamma-Ray Logs from Borehole 299-E13-2 at the 216-B-15 Crib | 3.64 |
| 3.2-16 | Comparison of 1999 and 1976 Gross Gamma-Ray Logs from Borehole 299-E13-4 at the 216-B-17 Crib | 3.65 |
| 3.2-17 | Comparison of 1999 and 1984 Gross Gamma-Ray Logs from Borehole 299-E13-289 at the 216-B-38 Crib | 3.66 |
| 3.2-18 | Comparison of 1999 and 1992 Gross Gamma-Ray Logs and Spectral Gamma-Ray Logs for Cesium-137 from Borehole 299-E33-290 at the 216-B-38 Trench | 3.67 |
| 3.3-1 | Cross Section of the Hanford Site Prototype Barrier Showing Interactive Water Balance Processes, Gravel Side Slope, and Basalt Riprap Slope | 3.77 |
| 3.3-2 | Temporal Variation in Mean Soil Water Storage at the Prototype Barrier, November 1994 to September 1998 | 3.78 |
| 3.3-3 | Cumulative Drainage from November 1994 through September 1998 from Four Side-Slope Plots and One Soil Plot that Drained | 3.78 |
| 3.3-4 | Location of Soil Gas Sampling Points Adjacent to Well 699-41-1 Near the Old Hanford Townsite | 3.79 |
| 3.3-5 | Helium-3/Helium-4 Ratios at the Study Site Near KE Reactor | 3.80 |
| 3.3-6 | Comparison of Helium-3/Helium-4 Ratios for Samples at the Old Hanford Townsite | 3.81 |
| 5.3-1 | Classification of Wells for Decommissioning | 5.5 |
| Plate 1 | Locations of Hanford Site Monitoring Wells | |
| Plate 2 | Hanford Site Water-Table Map, March 1999 | |
| Plate 3 | Tritium Map of the 300 Area of Hanford | |